



# FIRST INFORMATION REPORT

0665

(Under Section 154 Cr. P.C.)

1. P.S. Bhaktinagar Year 2024 FIR No. 1596/24 Date 20/12/2024

Sections..... (ii) Act..... Sections.....

(iii) Act..... Sections..... (iv) Other Acts & Sections 135(4)(b) The

3. [a] Occurrence of Offence : Day..... Date From 20/12/24 Date To Electronics Act.

Time Period at 13.30 hr Time From..... Time To.....

[b] Information received at P.S. Date 20/12/2024 Time 17.25 hr

[c] General Diary Reference : Entry No. (s) 1142 Time 17.25 hr

4. Type of Information :..... Written/Oral :.....

5. Place of Occurrence : (a) Direction and Distance from P.S..... Beat No.....

[b] Address Raj colony, Cheyan Para, PS Bhaktinagar, DPC

[c] In case outside limit of this Police Station, then the

Name of the P.S..... District.....

6. Complainant/Informant :

[a] Name Sri Suman Sengupta

[B] Father's / Husband's Name S/O Sri Haran Ashok Sengupta

[c] Date / Year of Birth..... [d] Nationality Indian

[e] Passport No..... Date of Issue..... Place of Issue.....

[f] Occupation Divisional Engineer (E)

[g] Address W.D. P.C.

7. Details of known / suspected / unknown accused with full particulars

(Attach separate sheet, if necessary):

Mamindra Ray, S/O Sri Haran Ray of Ray Colony more, Cheyanpara, Near Kalbari, PS Bhaktinagar, Dist: Jalpaiguri

8. Reasons for delay in reporting by the Complainant / Information

9. Particulars of properties stolen / involved (Attach separate sheet, if necessary)

10. Total value of properties stolen / involved.....

11. Inquest Report / U.D. Case No. If any.....

12. FIR Contents (Attach separate sheets, if required) The original written complaint which is treated as FIR is enclosed here with / reproduced / inserted with FIR

13. Action taken : Since the above report reveals commission of offence(s) as mentioned at item No.2, registered the case and took up the investigation / directed ACI NIRMAL to take up investigation / refuse investigation / transferred to P.S. BARMAN on point of jurisdiction. FIR read over to the Complaint / Informant, admitted to be correctly recorded and a copy given to the Complainant / Informant free of cost.

14. Signature / Thumb impression of the Complainant / Informant Noted in original complaint  
Signature of the Officer-in-Charge 20/12/24  
DR No. 6906 DT. 21/12/24  
Bhaktinagar Police Station  
Siliguri Metropolitan Police

Date & Time of despatch to the Commissionerate Name DAWA TSHERING SHERPA  
Rank SI OR POLICE No. BKN PJ/SDC





# West Bengal State Electricity Distribution Company Ltd.

(A government of West Bengal Enterprise)

Power House Customer Care Centre

2<sup>nd</sup> mile, Sevoke Road, Siliguri- 734 001

**WBSIEDCL**

Telephone No: 0353-2545861 (24 HRS), Call Center No: 1800-3453-206 (TOLL FREE), E-mail: powerhouse.siliguri@gmail.com

Memo No:- SM/STD/PHCC/FIR/1225

Date:- 20/12/2021

To  
The Inspector -In-Charge  
Bhaktinagar P.S.  
Dist-Darjeeling

Subject: F.I.R

Sir,

I, Suman Sengupta, Son of Ashoke Sengupta, D.E & SM Power House CCC, empowered by The Electricity Act 2003 amended on 2007 of India do here by lodge this complaint against Sri. Manindra Roy (ph no- 9476176586), S/O Sri Haren Roy, resident of Roy Colony more, Chayan Para, Near Kalibari, P.S Bhaktinagar, Dist Jalpaiguri, West Bengal. While on a routine inspection on the site having consumer id 401092587, meter no B2108487, having power connection by WBSIEDCL in the name of Sri. Manindra Roy in the address being Roy Colony more, Chayan Para, Near Kalibari, P.S Bhaktinagar, Dist Jalpaiguri, West Bengal, I, Suman Sengupta, Divisional Engineer & Station Manager, Power House CCC along with Sri Apurba Mitra, Junior Manager, Power House CCC, WBSIEDCL and other technical staffs observed that the terminal seal of the meter was broken and energy was being used bypassing the energy meter via direct hooking from service cable.

We entered the premises at 1340 hrs on 20.12.2021 after handing over Notice to Sri Manindra Roy. Then it was observed that the power was being used in an unauthorized manner via directly bypassing the energy meter and breaking the terminal seal of the energy meter via direct tapping from the service cable. Therefore committing a crime for theft of power as per section 135 (1) (b) of the Indian Electricity act 2003 amended on 2007. Accordingly the connection was disconnected and the energy meter and service cable were seized and labelled. A copy of both inspection report and Seizure list (1. Bentec Make Meter, 1 Phase, (240 Volts), (5-30) amps, SI No B2108487, property of WBSIEDCL, & 2. Service Cable of Black Color, 6 Sq mm, Single Stranded, Double Core Aluminium wire of 7 meters approx ) were handed over to Sri Manindra Roy. We exited the premises on 1355hrs.

Thus you are requested to kindly initiate an investigation against Sri. Manindra Roy under Section 135 (1) (b) of the Indian Electricity act 2003 amended on 2007 of India.

Yours faithfully

- Encl :-
1. Inspection Report
  2. Notice
  3. Seizure list
  4. Labelled seized articles

Suman Sengupta  
Divisional Engineer (E)  
Power House CCC  
WBSIEDCL

# WBSIEDCL

Registered Office: Bidyut Bhavan, Block-DJ, Sector-II, Bidhannagar, Kolkata- 700 091  
CIN: U40109WB2007SGC113473, Website: [www.wbsedcl.in](http://www.wbsedcl.in)

Recd on 20/12/21 at - 17:25 hr vide G.O. NO 1142  
at 20/12/21 we started Bktr PS case No 1596/21  
at 20/12/21 u/s 135 (1) (b) of Electricity Act  
we seized the same to ASI Nirajal & ...  
At investigation

Inspector-In-Charge  
Bhaktinagar Police Station  
Siliguri Metropolitan Police