

1909

1. Dist SPE P.S. Bagdogra Year 2023 FIR No. 359/23 Date 28-07-23

2. i) Act. Sections 136/1(a) of Indian Electricity Act. ii) Act. Sections

(iii) Act. Sections (iv) Others Acts & Sections

3. (a) Occurrence of Offence : Day Friday Date From 28-07-23 Date To

Time Period amd. Time From 10-30 hr Time To

(b) Information received at P.S. Date 28-07-23 Time 14-35 hr.

(c) General Diary Reference : Entry No(s) 1338 Time 14-35 hr

4. Type of Information : W Written / Oral

5. Place of Occurrence : (a) Direction and Distance from P.S. Beat No.

(b) Address Station More, Hula Bridge and Chikarajen High School under Bagdogra Ft. Dist Darjeeling

(c) In case outside limit of this Police Station, then the Name of the P.S. District

6. Complainant / Informant : (a) Name Sri Sumit Konez (M.No. 8900795086)

(b) Father's / Husband's Name Susanta Konez

(c) Date / Year of Birth (d) Nationality Indian

(e) Passport No. AE(E) & Station Manager, Bagdogra CC, WBSF DCL. Date of Issue Place of Issue

(f) Occupation Dingapur-1 PS-Lokoben Dist-Burdwan west.

(g) Address Pir-713201

7. Details of known / suspected / unknown accused with full particulars (Attach separate sheet, if necessary) : Unknown Misdemeanor

8. Reasons for delay in reporting by the Complainant / information

9. Particulars of properties stolen / involved (Attach separate sheet, if necessary) : 09 Nos. A porcelain cut out fuse unit 300A.

10. Total value of properties stolen / involved

11. Inquest Report / U.D. Case No., if any

12. FIR Contents (Attach separate sheets, if required) The original complaint of the complainant which is treated as an FIR is reproduced overleaf.

13. Action taken : Since the above report reveals commission of offence(s) as mentioned at item No. 2., registered the case and took up the investigation / directed Asst Ashish Karmakar to take up investigation / refused investigation / transferred to P.S. on point of jurisdiction. FIR read over to the Complainant/ Informant, admitted to be correctly recorded and a copy given to the Complainant / Informant free of cost.

14. Signature / Thumb impression Noted in written complaint


Signature of the Officer-in-Charge, Police Station Nirmal K. Das

Name : Nirmal K. Das

of the Complainant / Informant M.No. 8900795086

West Bengal State Electricity Distribution Company Limited
(A Government of West Bengal Enterprise)

Registered Office :
Bidyut Bhavan, Block - DJ
Sector - II, Bidhannagar
Kolkata - 700 091
CIN - U40109WB2007SGC113473



WBSEDCL

Website - www.wbsedcl.in

CCC Office : Bagdogra
Biharmore, Dist. - Darjeeling
Pin. - 734 014
E Mail - sm.bagdogra@gmail.com
Tel. / - 0353 2551276

Memo No-BCCC/E-15/ 219

To,
The Officer-in-Charge,
Bagdogra Police Station,
Bagdogra

Received on - 28-7-23 Date: 28.07.2023
note BDD of ADB No. 1338 dt-28-7-23
and over this started at Bagdogra P.S.
Case No-359/23 dt-28-07-23 U/S 361(a)
of Indian Electricity Act and endorsed
to ASI B. Kishor Kumar in-charge
of the case.

Officer-in-charge
Bagdogra P.S. S.I.G.
Siliguri Metropolitan Police

Sub: F.I.R for missing parts of Transformers at Station More, Hulia Bridge and Chittaranjan High School under Bagdogra CCC

Respected Sir,

While patrolling the line on 28.07.2023 around 10:30 AM, the maintenance team has noticed that some parts of the transformer structure at Station More, Hulia Bridge and Chittaranjan High School was missing.

For the transformer structure at Station More (DTR CODE: 5909P), the missing items are as follows:

Description	Quantity	Cost
Porcelain Cut Out Fuse Unit 300A	3 Nos	Rs. 7006.5

For the transformer structure at Hulia Bridge (DTR CODE: 5909U), missing parts are as follows:

Description	Quantity	Cost
Porcelain Cut Out Fuse Unit 300A	3 Nos	Rs. 7006.5


For the transformer structure at Chittaranjan High School (DTR CODE: 5909X), missing parts are as follows:

Description	Quantity	Cost
Porcelain Cut Out Fuse Unit 300A	3 Nos	Rs. 7006.5

For stable operation of transformers these parts are essential. Therefore, I would request you to investigate the matter as some unknown miscreant might have stolen these parts from existing structures and treat this as F.I.R. under S/C 136/1(a) of The Indian Electricity Act. For details of location of the transformers maintenance team supervisor Manoj Sharma (Mb. No: 7718681146) may be contacted.

Enclosure: Images of the transformers with stolen parts.

SUMIT KONER
S/O - SUSANTA KONER
SURJOSAN PALLY
P.O - DURGAPUR - I


(SUMIT KONER)
AE(E) &
Station Manager
Bagdogra CCC