(Under Section 154 Cr. P.C.) SPE Mahigara Year 2021 FIR No. 815/2021 Date 04.08.2021 X Sections ii) Act Electriculis Actions 136 Buch Sections (iv) Others Acts & Sections Cilis Bet (B ment (iii) Act Time Period......Time From (b) Information received at P.S. Date 04-08-2021 Time 21:50 h 5. Place of Occurrence : (a) Direction and Distance from P.S. / KM North Beat No. (b) Address 11 KV/433V Motajole Matrgare Psmatigaro/Dsh. (c) In case outside limit of this Police Station, then the Name of the P.S. N/D. District 6. Complainant / Informant : (a) Name Abhishek Roy (b) Father's / Husband's Name/ (f) Occupation A EX Station Manager

(g) Address Mahigara Cuetomer Care Center DS-M74/D54. Defails of known / suspected / unknown accused with full particulars (Attach separate sheet, if necessary): Uhkumu person Reasons for delay in reporting by the Complainant / Information Particulars of properties stolen / involved (Attach separate sheet, if necessary) : Traiformer Oil 10. Total value of properties stolen / involved 11. Inquest Report / U.D. Case No., if any 12. FIR Contents (Attach separate sheets, if required): The Original writer Complain Which is freeded as fire is enclosed here with investigation / refused investigation / transferred to P.S. PS/Spc jurisdiction. FIR read over to the Complaint/ Informant, admitted to be correctly recorded and a copy given to the Complainant /

14. Signature / Thumb impression of the Complainant / Informant

Signature of the Officer-in-Charge Police Station

Bengal State Electricity Distribution Company Limited (A Government of West Bengal Enterprise)

stered Office:
stdyut Bhavan, Biock – DJ
Sector – II, Bidhannagar
Kolkata – 700 091
CIN – U40109WB2007SGC113473



Matigara Customer Care Centre Hospital more,Old Matigara Road, Matigara, Darjeeling.Pin. – 734 010 E Mail – sm.matigara@gmail.com Tel. – 03532571699/03532571054

Website - www.wbsedcl.in

Memo No :-SM/CCCM/FIR/21-22/ 266

Date: 04.08.2021

To
The Officer In charge,
Mtigara Police Station,
Thana more, Matigara,
Dist: Darjeeling.

Sub:-Information regarding Oil theft from Distribution Transformer 11 KV/433V at Motajote, Matigara under Matigara CCC.

Dear Sir,

It has been found that Distribution Transformer at Motajote, Matigara S/S NO S-39-0049-0 under Matigara CCC has got defective on 04.08.2021 and the DTR was isolated form 11 KV system. During inspection against power outage complaint it has been found that the oil of transformer (Industrial Meters Pvt Ltd, SI no : 9076 MFG 1988) is drained by a pipe attached to it which causes the transformer burnt and resulting malfunction. The circuit of the Distribution Transformer was energised from nearest Transformer from 10.00 am to 12.00 pm after that another heathly 100 KVA transformer is installed to replace the transformer at Motajote.

You are therefore requested to keep this information and take necessary action.

Received On. 4/8/2021 at 21.50 h

vide GDE NO 210 Dt 4/8/1021

and Started Makigara PS (come

NO. 8/5/2021 D1. 09/8/2021 MS

136 Electricity Def (Devendant

2007) and endown to 841

Abdul Lahif finils Muhiguta;

Yours faithfully

04108/21

(Abhishek Roy

AE & Station Manager,

Matigara CCC.

Mob: 8900795083

Asst. Engineer (E) Station Manager Matigara CCC W.B.S.E.D.C.L

OP () U U
Officer In-Charge
Matigara Police Station
Sulguri Police Commissionerate