

FIRST INFORMATION REPORT

(Under Section 154 Cr. P.C.)

0671



1. Dist. SDC P.S. Bhabanagar Year 2021 FIR No. 1602/2 Date 21/12/2021
2. (i) Act Sections (ii) Act Sections
(iii) Sections (iv) Other Acts & Sections 135(a), (b) Electricity Act

3. Occurrence of Offence : Day Date From 21/12/21 Date To Act-
Time Period at 12.50 hrs Time From Time To

[b] Information received at P.S. Date 21/12/2021 Time 15.30 hrs

[c] General Diary Reference : Entry No. (s) 1194 Time 15.30 hr

4. Type of Information : Written / Oral

5. Place of Occurrence : (a) Direction and Distance from P.S. Beat No.

[b] Address Baikuntha colony, Sarokee Road, District Bhabanagar PS Jalepiganj

[c] In case outside limit of this Police Station, then the Name of the P.S. District

6. Complainant / Informant :

[a] Name Sri Suman Sengupta

[B] Father's / Husband's Name S/o. Ashok Sengupta

[c] Date / Year of Birth [d] Nationality Indian

[e] Passport No. Date of Issue Place of Issue

[f] Occupation Divisional manager (RR)

[g] Address C/3 BSEDEL

7. Details of known / suspected / unknown accused with full particulars

(Attach separate sheet, if necessary):

Bikram Tewari s/o Sri Anagnath Tewari of Baikuntha colony p.o Sarokee Road PS Bhabanagar Jalepiganj

8. Reasons for delay in reporting by the Complainant / Information

9. Particulars of properties stolen / involved (Attach separate sheet, if necessary)

10. Total value of properties stolen / involved

11. Inquest Report / U.D. Case No. If any

12. FIR Contents (Attach separate sheets, if required) The original written complaint which is treated as FIR is enclosed here with reproduced over leaf

13. Action taken : Since the above report reveals commission of offence(s) as mentioned at item No.2, registered the case and took up the investigation / directed ASI ASIT SAHA to take up investigation / refuse investigation / transfered to P.S. on point of jurisdiction. FIR read over to the Complainant / Informant, admitted to be correctly recorded and a copy given to the Complainant / Informant free of cost.

14. Signature / Thumb impression of the Complainant / Informant
Notes in original complaint

Inspector Dhakinagar Siliguri Metropolitan Police Station

Date & Time of despatch to the court

Name DAWA THERING SHEPA Rank ST/OP POLICE No. BK N 51524



West Bengal State Electricity Distribution Company Ltd.

(A government of West Bengal Enterprise)

Power House Customer Care Centre

2nd mile, Sevoke Road, Siliguri- 734 001

WBSEDCL

Telephone No: 0353-2545861 (24 HRS), Call Center No: 1800-3453-206 (TOLL FREE), E-mail: powerhouse.siliguri@gmail.com

Memo No:- SM/STD/PHCC/FIR/ 2 2 T

Date:- 21/12/2021

To
The Inspector -In-Charge
Bhaktinagar P.S.
Dist-Darjeeling

Subject: F.I.R

Sir,

I, Suman Sengupta, Son of Ashoke Sengupta, D.E & SM Power House CCC, empowered by The Electricity Act 2003 amended on 2007 of India do here by lodge this complaint against Sri. Bikram Tewari (ph no- 9832390640/9641506763), S/O Sri Meghnath Tewari, resident of Baikunthapally, P.O. Sevoke Road, P.S Bhaktinagar, Dist Jalpaiguri, West Bengal. While on a routine inspection on the site having consumer id 402726351, meter no H00109819, having power connection by WBSEDCL in the name of Sri. Bikram Tewari in the address being Baikunthapally, P.O. Sevoke Road, P.S Bhaktinagar, Dist Jalpaiguri, West Bengal, I, Suman Sengupta, Divisional Engineer & Station Manager, Power House CCC along with Md Azharuddin, Junior Engineer (Gr. II), Power House CCC, WBSEDCL and other technical staffs observed that the terminal seal of the meter was broken and energy was being used bypassing the energy meter.

We entered the premises at 1305 hrs on 21.12.2021 after handing over Notice to Sri Ram Gopal Saha, Staff of Sri Bikram Tewari. Then it was observed that the power was being used in an unauthorized manner via directly bypassing the energy meter and breaking the terminal seal of the energy meter via direct tapping from the service cable. Therefore committing a crime for theft of power as per section 135 (1) (b) of the Indian Electricity act 2003 amended on 2007. Accordingly the connection was disconnected and the energy meter and service cable were seized and labelled. A copy of both inspection report and Seizure list (1. HPL Make Meter, 1 Phase, (240 Volts), (5-30) amps, SI No H00109819, property of WBSEDCL, & 2. Service Cable of Black Color, 6 Sq mm, Single Stranded, Double Core Aluminium PVC wire of 15 meters approx) were handed over to Sri Ram Gopal Saha. We exited the premises on 1345hrs.

Thus you are requested to kindly initiate an investigation against Sri. Bikram Tewari under Section 135 (1) (b) of the Indian Electricity act 2003 amended on 2007 of India.

- Encl :-
1. Inspection Report
 2. Notice
 3. Seizure list
 4. Labelled seized articles

Yours faithfully

Suman Sengupta
Divisional Engineer (E)
Power House CCC
WBSEDCL

WBSEDCL

Registered Office: Bidyut Bhavan, Block-DJ, Sector-II, Bidhannagar, Kolkata- 700 091

CIN: U40109WB2007SGC113473, Website: www.wbsecl.in

Received on 21/12/21 at 15:30 hrs vide G.O. NO 1194 dt 21/12/21

and started Blank PS case NO 1602/21 dt 21/12/21 U/S

135 (1) (b) of Electricity Act and endorsed the

same to ASI Asit Saha for its investigation

Inspector-In-Charge
Bhaktinagar Police Station
21/12/21
Siliguri Metropolitan Police