

FIRST INFORMATION REPORT
(Under Section 154 Cr. P.C.)

2907



Dist. EPC P.S. Bhaktinagar Year 2022 FIR No. 485/22 Date 12/05/2022

i) Act Sections _____ ii) Act Sections _____
(No. Act) _____ (iv) Others Acts & Sections 135(1)(a)/150

3 (a) Occurrence of Offence : Day _____ Date From _____ Date To Electrically Ad
Time Period _____ Time From 12/05/22 Time To 2005 Amendment
2007

(b) Information received at P.S. Date at 11.54 hr. Time 16.30 hr
(c) General Diary Reference : Entry No(s) 713 Time 16.30 hr

4. Type of Information : _____ Written / Oral

5. Place of Occurrence : (a) Direction and Distance from P.S. _____ Beat No. _____

(b) Address Boneswar more. PS Bhaktinagar Dist. Jalpaiguri

(c) In case outside limit of this Police Station, then the
Name of the P.S. _____ District _____

6. Complainant / Informant :

(a) Name Sri Suman Sengupta

(b) Father's / Husband's Name S/O Ashok Sengupta

(c) Date / Year of Birth _____ (d) Nationality Indian

(e) Passport No. _____ Date of Issue _____ Place of Issue _____

(f) Occupation D.E (L)

(g) Address Power House CCC, WBSEDCL.

7. Details of known / suspected / unknown accused with full particulars

(Attach separate sheet, if necessary) :
Dhanjay Ray (9832802456) S/O Lt Lugendra Nath Ray
of Boneswar more. PS Bhaktinagar. Jalpaiguri

8. Reasons for delay in reporting by the Complainant / Information

9. Particulars of properties stolen / involved (Attach separate sheet, if necessary) :

10. Total value of properties stolen / involved _____

11. Inquest Report / U.D. Case No., if any _____

12. FIR Contents (Attach separate sheets, if required) : The original written complaint which is
attached as FIR is enclosed herewith
reproduced over leaf

13. Action taken : Since the above report reveals commission of offence(s) as mentioned at item No. 2., registered the case and took
up the investigation / directed ASI AMIT MALLICK to take up

investigation / refused investigation / transferred to P.S. ASHISHAR OP on point of

jurisdiction. FIR read over to the Complainant/ Informant, admitted to be correctly recorded and a copy given to the Complainant /

Informant free of cost.

Note in original complaint

14. Signature / Thumb impression _____
of the Complainant / Informant

Inspector-In-Charge
Bhaktinagar Police Station
Signature of the Officer-in-Charge, Commissionerate

Name : DAWA TSHERING SHERPA

Rank : No. SI OF POLICE
1314 PS/SDC

15. Date & Time of despatch to the court :



West Bengal State Electricity Distribution Company Ltd.

(A government of West Bengal Enterprise)

Power House Customer Care Centre

2nd mile, Sevoke Road, Siliguri- 734 001

Telephone No: 0353-2545861 (24 HRS), Call Center No: 1800-3453-206 (TOLL FREE), E-mail: powerhouse.siliguri@gmail.com

Date:- 12/05/22

Memo No:- SM/STD/PHCC/FIR/ 201

To
The Inspector -In-Charge
Bhaktinagar P.S.
Dist-Darjeeling

Subject: F.I.R

Sir,
I, Suman Sengupta, Son of Ashoke Sengupta, D.E & SM Power House CCC, empowered by The Electricity Act 2003 amended on 2007 of India do here by lodge this complaint against Sri. Dhananjay Roy (ph no- 9832802456), S/O Lt Ligendra nath Roy, resident of Banerwar More, P.S Bhaktinagar, Dist Jalpaiguri, West Bengal & Sri Bijoy Kumar Mondal, S/O Of not known, having a connection vide consumer id 400013742 at Banerwar More, Dist Jalpaiguri, PS Bhaktinagar. While on a routine inspection on the site having consumer id 412131294, meter no OB4558563, having power connection by WBSEDCL in the name of Sri. SMT. CHILAI SWARI ROY (Mother of Sri Dhananjay Roy) in the address being Banerwar More, P.S Bhaktinagar, Dist Jalpaiguri, West Bengal, Which is currently being enjoyed by Sri Dhananjay Roy, I, Suman Sengupta, Divisional Engineer & Station Manager, Power House CCC along with Sanjay Prasad, Sr Office Executive, Power House CCC, WBSEDCL and other technical staffs observed that the power from the said meter was being provided in a different disconnected premises having outstanding dues of Sri Bijoy Kumar Mondal.


We entered the premises at 1154 hrs on 12.05.2022 after handing over Notice to Sri Dhananjay Roy. Then it was observed that the power was being used in an unauthorized manner, by providing power to a different premises where the power was not authorized for. A connection having consumer id 400013742 by the name of Sri Bijoy Kumar Mondal was prevailing beside the premises of Sri Dhananjay Roy, it has been disconnected due to an Outstanding Of Rs 48409/-. A cable was found extended from the premises of Sri Dhananjay Roy to the premises of Sri Bijoy Kumar Mondal, providing power to the disconnected premises un authorized. Therefore committing a crime for theft of power as per section 135 (1) (e) of the Indian Electricity act 2003 amended on 2007. Accordingly the connection was disconnected and the energy meter and service cable were seized and labelled. A copy of both inspection report and Seizure list (1. Bentec make, SI No OB4558563, 1 Phase, (240 Volts), (5-30) amps, property of WBSEDCL, & 2. Service Cable of Black & Red In Color, 10 Sq mm, Single Stranded, Double Core Aluminium PVC wire of 20 meters approx) were handed over to Sri Dhananjay Roy. We exited the premises at 1245hrs.


Thus you are requested to kindly initiate an investigation against Sri. Dhananjay Roy under Section 135 (1) (e) of the Indian Electricity act 2003 amended on 2007 of India & against Sri Bijoy Kumar Mondal under Section 150 of the Indian Electricity act 2003 amended on 2007 of India.

- Encls :-
1. Inspection Report
 2. Notice
 3. Seizure list
 4. Labelled seized articles

Received on 12/05/22 at 16:30 hr vide
ADG NO 713 dt 12/05/22 and started
Bkn PS case NO 485/22 dt
12/05/22 u/s 135(1)(e)/150 Electricity
Act 2003 Amended on 2007 and
endorsed the same to ASI
Anand Mallick for his
investigation

Yours faithfully


Suman Sengupta
Divisional Engineer (E)
Power House CCC
WBSEDCL


Inspector In-Charge
Bhaktinagar Police Station
Siliguri Police Commissionerate