

FIRST INFORMATION REPORT
(Under Section 154 Cr. P.C.)



1829 Jageeling / C

P.S. Siliguri Year 2023 FIR No. 627/23 Date 06/08/23

Sections 136 of the Indian Electricity Act, 2003

(a) Occurrence of Offence : Day Date From 06/08/23 Date To Time Period Time From Time To

(b) Information received at P.S. Date 06/08/23 Time 22:50 hrs.
(c) General Diary Reference : Entry No(s) 334 Time 22:50 hrs.

4. Type of Information : Written / Oral

5. Place of Occurrence : (a) Direction and Distance from P.S. Beat No.
(b) Address Bidhan Road (Shantiniketan) & Airview More (near 3gen diagonashc

(c) In case outside limit of this Police Station, then the Name of the P.S. District

6. Complainant / Informant :
(a) Name Si Tapas Bishui
(b) Father's / Husband's Name Lt. Brendra Nath Bishui
(c) Date / Year of Birth : (d) Nationality INDIAN
(e) Passport No. Date of Issue : Place of Issue :
(f) Occupation Assistant Engineer & station Manager
(g) Address Siliguri Town CCC, WBSEDEL under Siliguri P.S.

7. Details of known / suspected / unknown accused with full particulars
(Attach separate sheet, if necessary) :
Unknown Miscreants.

8. Reasons for delay in reporting by the Complainant / Information

9. Particulars of properties stolen / involved (Attach separate sheet, if necessary) :
Office & Moving Contact (200A) - 1 set (3nos) @ Flexible Cord (Cu Braided wire) - 1 set @ Fuse Unit (HT) - 1 set.

10. Total value of properties stolen / involved Rs 10,400/-

11. Inquest Report / U.D. Case No., if any

12. FIR Contents (Attach separate sheets, if required) : The original written complaint of the complainant is treated as FIR which is enclosed herewith

13. Action taken : Since the above report reveals commission of offence(s) as mentioned at item No. 2., registered the case and took up the investigation / directed ASI Samir kr Mandal of Siliguri P.S. to take up investigation / refused investigation / transferred to P.S. on point of jurisdiction. FIR read over to the Complainant/ Informant, admitted to be correctly recorded and a copy given to the Complainant / Informant free of cost.

Noted in original complaint

14. Signature / Thumb impression of the Complainant / Informant

On 07/08/23 at 10:30hrs.

15. Date & Time of despatch to the court :

Signature of the Officer-in-Charge, Police Station

Name : Inspector in Charge
Rank : No. Siliguri Police Station
Assistant Police Commissioner



WEST BENGAL STATE ELECTRICITY DISTRIBUTION COMPANY LIMITED
(A Government of West Bengal Enterprise)
SILIGURI TOWN CUSTOMER CARE CENTRE

✉ : siliguritownccc@gmail.com
☎ -0353-2431006

Memo No. SM/STCCC/Theft/23-24/250

Date: 06.08.2023

To
The Inspector - In - Charge
Siliguri Police Station
Siliguri, Dist. Darjeeling.

Subject:- Complaint for theft of Electrical accessories from transformer Structure located at Bidhan Road (Shantiniketan S/S, 2x100KVA, FW015, FW048)) and Airview More (3 gen diagnostic 1X100KVA, FW02L) P.S. Siliguri, Dist. Darjeeling-734001 under Siliguri Town CCC, WBSEDCL.

Sir,

I, Sri Tapas Bishui, S/O-Late Birendra Nath Bishui, Assistant Engineer & Station Manager, Siliguri Town CCC, WBSEDCL under Siliguri P.S., empowered by the Electricity Act 2003 (Amended Act 2007) do hereby lodge this complaint for the theft of property of WBSEDCL by unknown miscreants from three(3) Transformer Structures at Bidhan Road (Shantiniketan S/S, 2x100KVA) and Airview More (near 3 gen diagnostic S/S, 1X100KVA). Today (06.08.2023) morning near about 8.30AM, call was received for "No Power" from these three (3) transformer area and our Mobile Van went to the sites and they have found such missing of electrical equipments from the live transformer Structure. They immediately reported the matter to me. We could not trace the miscreants. However, we have restore the power within three hours after getting the report. In view of the safety this type of activity is very dangerous for the person doing this misdemeanor and also for the local people too. This wicked act caused financial loss of the WBSEDCL of Rs. 10,400/- (Rupees ten thousand four hundred only).

List of materials missing from the Transformer Structures:

- 1) Fix & Moving Contact (200A) – 1 Set (3 nos.) DTR CODE: FW02L, FW015, FW048 (total 9 sets)
- 2) Flexible Cord (Cu Bradded wire) – 1Set (3 nos.) DTR ODE: FW02L, FW015, FW048 (total 9 nos.)
- 3) Fuse Unt (HT) – 1 Set (6 nos. PIN Insulator) DTR CODE: FW015, FW048 (total 12 nos.)

As the theft of Electrical Materials detected, you are requested to initiate investigation against the miscreants under section 136 of the Indian Electricity Act 2003 amended on 2007.

Received on 06/08/23 at 22:50hrs.
vide Slg PS GDE no - 334 dt - 06/08/23
and started Slg PS Case no - 627/23 S/O
dt - 06/08/23 U/S 136 of the Indian
Electricity Act, 2003 and addressed to
ASI Samir Kumar Mandal for its
investigation.

Yours faithfully,
Tapas Bishui
(Tapas Bishui) 06/08/2023
A.E & S. M, ST CCC
S/O Lt. Birendra Nath Bishui
Mob. No. 8900795068

Dm
06-8-23
Inspector-In-Charge
Siliguri Police Station
Siliguri Police Commissionerate