


FIRST INFORMATION REPORT  
(Under Section 154 Cr. P.C.)

103

1. Dist. Darjeeling P.S. Siliguri Year. 2023 FIR No. 65/23 Date 10/8/2023  
2. i) Act X Sections X ii) Act Electricity Act, 2003 Sections 136(D)/140  
iii) Act X Sections X (iv) Others Acts & Sections X



3. (a) Occurrence of Offence : Day - Date From - Date To 10/8/2023  
Time Period - Time From - Time To 02:15 Pms.  
(b) Information received at P.S. Date 10/8/2023 Time 22:10 Pms.  
(c) General Diary Reference : Entry No(s) 581 Time 22:10 Pms.

4. Type of Information Written Written / Oral

5. Place of Occurrence : (a) Direction and Distance from P.S. 01 KM approx Beat No. -  
(b) Address S.F. Road (Orchid Plaza, Shyam Plaza, Near Ananda Lake Shanti  
P.S. Maidin, Thana more near Radha Bazar and Jagadik Market), P.S. Siliguri  
(c) In case outside limit of this Police Station, then the X  
Name of the P.S. - District -

6. Complainant / Informant :  
(a) Name Prashanta Kumar Mahato  
(b) Father's / Husband's Name Dilip Kumar Mahato  
(c) Date / Year of Birth : ..... (d) Nationality Indian  
(e) Passport No. .... Date of Issue : ..... Place of Issue .....  
(f) Occupation Assistant Engineer & Station Manager,  
(g) Address Milanpally ccc, WBSEDC

7. Details of known / suspected / unknown accused with full particulars Unknown miscreant.  
(Attach separate sheet, if necessary) :

8. Reasons for delay in reporting by the Complainant / Information -

9. Particulars of properties stolen / involved (Attach separate sheet, if necessary) : 15 nos. of fixed and moving  
contact of Isolator amounting of Rs. 13,755/- and 15 nos. of Copper Flexi-  
ble Braided Tape amounting of Rs. 5,745/-.

10. Total value of properties stolen / involved Rs. 19,500/- (Nineteen Thousand five hundred) only

11. Inquest Report / U.D. Case No., if any X

12. FIR Contents (Attach separate sheets, if required) : The original written complaint of  
the complainant which has been treated as FIR is  
enclosed herewith.

13. Action taken : Since the above report reveals commission of offence(s) as mentioned at item No. 2., registered the case and took  
up the investigation / directed ASI Samiran Das. to take up  
investigation / refused investigation / transferred to P.S. - on point of  
jurisdiction. FIR read over to the Complainant/ Informant, admitted to be correctly recorded and a copy given to the Complainant /  
Informant free of cost.

14. Signature / Thumb impression Noted in original complaint,  
of the Complainant / Informant

15. Date & Time of despatch to the court : On 11.8.2023 at 10:30 Pms.

X 10/8/2023  
Signature of the Officer-in-Charge, Police Station

Name : DEBABRATA SENGUPTA  
Rank : No. S.I. OF POLICE  
Siliguri Police Commissionerate



**WEST BENGAL STATE ELECTRICITY DISTRIBUTION CO. LTD.**  
(A Govt. of West Bengal Enterprise)  
**OFFICE OF THE ASSISTANT ENGINEER MILANPALLY C.C.C**

**WBSEDCL**

Phone Number: 0353-2561036, E-mail ID: emmpgoc@gmail.com

Memo No.: AE/MPCCC/PS/Theft/2605

dated 10.08.2023

To,  
The Officer-in-Charge,  
Khalpara TOP  
Siliguri

Received on 10.8.2023 at 22:10 hrs. vide Siliguri Ps  
Siliguri Ps GDE no. 581, date 10.8.23 and started Siliguri  
Ps case no. 651/23, date 10-8-23, u/s 136(1)/140 Elec-  
tricity Act, 2003. Asl Sanjivan Das has been entered for investigation.

Subject: FIR regarding the theft of high voltage materials from Distribution Transformer Double Pole Structure at S.F. Road | Transformer Code - CR08E (Orchid Plaza, SF Road), CR08B (Shyam Plaza), CR00W (Near Anandaloke Shani Mandir), CR04C (Thana More near Radha Bazaar), CR098 (Jajodia Market, SF Road) early morning on 10th August, 2023.

Sir,

This is to inform you that early morning today (10th August, 2023) at around 02:15 am, theft of High Voltage Materials has occurred from FOUR different Distribution Transformer Double Pole Structure at S.F. Road | Transformer Code - CR08E (Orchid Plaza, SF Road), CR08B (Shyam Plaza), CR00W (Near Anandaloke Shani Mandir), CR04C (Thana More near Radha Bazaar), CR098 (Jajodia Market, SF Road).

Power failure dockets were registered by consumers at 02:35 am against which our LT mobile van maintenance team visited the spot at SF Road to restore the power but found that HT materials were missing from Double Pole Structure. The materials which are stolen from the site includes Isolator contact and Flexible Chord.

Material Code	Description	Rate	Nos	Amount
0304042532	Fixed and Moving Contact of Isolator	917	15	13,755
0304043341	Copper Flexible Braided Tape	383	15	5,745
TOTAL				19,500

Total loss incurred by WBSEDCL is Rs. 19,500/- only  
You are therefore requested to treat this as an FIR and an investigation u/s 136 (1) / 140 of Electricity Act, 2003

Prashanta K. Mahato  
10/8/23  
Assistant Engineer  
& Station Manager  
Milanpally CCC  
W.B.S.E.D.C. Ltd.  
Prashanta Kumar Mahato  
s/o- Dilip Kumar Mahato  
8900795070  
Assistant Engineer & Station Manager,  
Milanpally CCC  
WBSEDCL

Received on 10.08.23 at 21:45 hrs.  
vide Khalpara TOP G.D.E. No. 732  
dt. 10.08.23 and forwarded to JTC  
SLP PS. to start a specific case  
under proper sec. of Law.

*[Signature]*  
10/08/23

Officer-in-Charge  
Khalpara TOP  
Siliguri