

FIRST INFORMATION REPORT
(Under Section 154 Cr. P.C.)

5034



Dist. Bhaktinagar Year 2022 FIR No. 1001/22 Date 14/9/2022
i) Act IPC Sections 336 ii) Act - Sections -
iii) Act - Sections - (iv) Others Acts & Sections -

3. (a) Occurrence of Offence : Day 14-9-2022 Date To -
Time Period 15:15 hrs. Time To -
(b) Information received at P.S. Date 14-9-2022 Time 18:35 hrs.
(c) General Diary Reference : Entry No(s) 599 Time 18:35 hrs.

4. Type of Information - Written / Oral

5. Place of Occurrence : (a) Direction and Distance from P.S. - Beat No. -

(b) Address House of Chandan Saha at near Ektiasal Hat, South Ektiasal, PS- Bhaktinagar, Dist- Jalpaiguri.

(c) In case outside limit of this Police Station, then the Name of the P.S. - District -

6. Complainant / Informant :

(a) Name Sri Suman Sengupta
(b) Father's / Husband's Name Ashoke Sengupta
(c) Date / Year of Birth - (d) Nationality Indian
(e) Passport No. - Date of Issue - Place of Issue -
(f) Occupation Service
(g) Address Divisional Engineer (E) & S.M, Power House C.E.C. NRSEDEL, 2nd Mile Servotia Road, PS- Bhaktinagar, Dist- Jalpaiguri.

7. Details of known / suspected / unknown accused with full particulars
(Attach separate sheet, if necessary) :
Chandan Saha, near Ektiasal Hat, South Ektiasal, PS- Bhaktinagar, Dist- Jalpaiguri.

8. Reasons for delay in reporting by the Complainant / Information -

9. Particulars of properties stolen / involved (Attach separate sheet, if necessary) : -

10. Total value of properties stolen / involved -

11. Inquest Report / U.D. Case No., if any -

12. FIR Contents (Attach separate sheets, if required) : The original written Complaint of the Complainant which is treated as F.I.R is reproduced overleaf.
14/9/22

13. Action taken : Since the above report reveals commission of offence(s) as mentioned at item No. 2., registered the case and took up the investigation / directed Asi Ujjal Mandal of ASG SP. to take up investigation / refused investigation / transferred to P.S. - on point of jurisdiction. FIR read over to the Complainant/ Informant, admitted to be correctly recorded and a copy given to the Complainant / Informant free of cost.

14. Signature / Thumb impression Moti in original Complaint. of the Complainant / Informant
Inspector in Charge
Signature of the Officer-in-Charge, Police Station
Bhaktinagar Police Station
Siliguri Police Commissionerate
Name : Amresh Singh
Rank : No. 1/c, Bhaktinagar PS

15. Date & Time of despatch to the court :



West Bengal State Electricity Distribution Company Ltd.

(A government of West Bengal Enterprise)

Power House Customer Care Centre

2nd mile, Sevoke Road, Siliguri- 734 001

Telephone No: 0353-2545861 (24 HRS), Call Center No: 1800-3453-206 (TOLL FREE), E-mail: powerhouse.siliguri@gmail.com

Merno No:- SM/STD/PHCC/FIR/261

Date:- 14.09.22

To

The Inspector -In-Charge

Bhaktinagar P.S.

Dist-Darjeeling

Subject: F.I.R

Sir,

I, Suman Sengupta, Son of Ashoke Sengupta, D.E & SM Power House CCC, do here by lodge this complaint against SRI CHANDAN SAHA, NR-EKTIASAL HAT, SOUTH EKTIASAL, P.S. BHAKTINAGAR, SLG - 734001 (Mob: 9749401351/8918753354). While on a routine inspection of the site at NR-EKTIASAL HAT, SOUTH EKTIASAL, P.S. BHAKTINAGAR, P.O. SEVOKE ROAD, SLG-734001 at around 03:15pm on 14.09.2022, I, Suman Sengupta, Divisional Engineer & Station Manager, Power House CCC along with other technical staffs observed that the house of SRI CHANDAN SAHA has been extended in an unauthorized manner hampering the safety clearance of the electrical installations of WBSEDCL. As per Indian Electricity Rules 1956, 80 (1) (a) a minimum vertical clearance of 3.7 meters & under 80 (2)(a) a minimum horizontal clearance of 1.2 meter was to be maintained between any part of the building and the Low And Medium Voltage Lines and networks of WBSEDCL. But the unauthorized encroachment of the LT Pole & LTABC has resulted in violation of the standards as per Indian Electricity Rules 1956, 80 (1) (a) & (2)(a). This violation may cause terrible outcomes in respect to safety hazards that will result in accidents, which might be fatal in nature.


Thus you are requested to kindly initiate an investigation against SRI MOHAN PAL, by treating this as F.I.R. This is for your information and necessary action please.

Yours faithfully

Encl :- 1. Photographs of the site

Received on 14/9/22 at 18.35 hrs.
vide BUN PL GDE NO-599 and
started Bhaktinagar PS case NO -
1001/22 date 14/9/22 u/s- 336 IPC.
Asi Ujjl Mandal of Ashighar OP
will investigate the case.

14/9/22
Inspector in-charge
Bhaktinagar Police Station
Siliguri Police Commissionerate


Suman Sengupta
Divisional Engineer (E)
Power House CCC
WBSEDCL
Ph-8900795066