

FIRST INFORMATION REPORT

(Under Section 154 Cr. P.C.)

1330

1. Dist SPC P.S. Bhaktinagar Year 2024 FIR No. 80/24 Date 01/02/24

2-i) Act - Sections - ii) Act - Sections -

iii) Act - Sections - iv) Others Acts & Sections 339 of the Indian Electricity Act 2003

3. (a) Occurrence of offence : Day Thursday Date From 01/02/24 Date To at mend 08:00 hrs

Time Period - Time From 16:15 hrs Time To 16:15 hrs

(b) Information received at P.S. Date 01/02/24 Time 16:15 hrs

(c) General Diary Reference : Entry No (s) 33 Time 16:15 hrs

4. Type of Information typed Written / ~~Oral~~

5. Place of Occurrence : (a) Direction and Distance from P.S. - Beat No. -

(b) Address Amala Man Road, Bowbazar, North Shaktinagar (Landmark - Shil' Bari)

(c) In case outside limit of this Police Station, then the Name of the P.S. - District -

6. Complainant / Informant :

(a) Name Sourav Paul

(b) Father's / Husband's Name Subrata Paul

(c) Date / Year of Birth - (d) Nationality Indian

(e) Passport No. - Date of Issue - Place of Issue -

(f) Occupation DE (E) & SM, Subhaspally CCC

(g) Address WBSEDCL

7. Details of known / suspected / unknown accused with full particulars

(Attach separate sheet, if necessary): Driver of the vehicle bearing registration NO - WB 73E 0179.

8. Reasons for delay in reporting by the Complainant / information -

9. Particulars of properties stolen / involved (Attach separate sheet, if necessary):

10. Total value of properties stolen / involved Rs 22,000/- (Twenty Two Thousand) approx.

11. Inquest Report / U.D. Case No. If any -

12. FIR Contents (Attach separate sheets, if required): The original typed complaint which is treated as FIR is attached herewith.

13. Action Taken : Since the above report reveals commission of offence(s) as mentioned at item No. 2, Registered the case and took up the investigation / directed ASI Sanjib Santra investigation / refused investigation / transferred to P.S. Ashigon OP under Bhaktinagar PS on point of jurisdiction. FIR read over to the Complaint / Informant, admitted to be correctly recorded and a copy given to the Complainant / informant free of cost.

14. Signature / Thumb impression of the Complainant / Informant is on the complaint Signature of the Officer-in-Charge, Police Station Pl. AMARESH SINGH

15. Date & Time of despatch to the court : DR No. 592 Date 01/02/24 Rank : No. IC Bhaktinagar PS, SPC

West Bengal State Electricity Distribution Company Limited

(A Government of West Bengal Enterprise)

CCC Office:

Office of the Station Manager, Subhaspally CCC, WBSEDCL,
1, Pritilata Road, Dabgram, Siliguri,
Dist- Darjeeling, PIN- 734006,
E Mail: spccc.slg@gmail.com,
Tel.: 0353-2596057



**OFFICE OF THE STATION MANAGER
SUBHASPALLY CCC**

Registered Office:

Vidyut Bhavan, Block -DJ
Sector-II, Bidhannagar,
Kolkata - 700 091
CIN - U40109WB2007SGC113473
Website- www.wbsecl.in

MEMO No - SPCCC/ 388

DATE - 01/02/2024

To

The Officer-in-Charge,
Ashighar Police Out-post (under Bhaktinagar PS, Siliguri Police Commissionerate),
Ashighar, Dist. - Jalpaiguri

Sub: - FIR for damage to WBSEDCL's Network by the Vehicle (Reg. No.: WB73E 0179) at Amtala Main Road, Bowbazar, North Shantinagar (Landmark: Shil Bari More) on 01.02.2024 around 08:00 am

Dear Sir,

This is to bring to your kind attention that a school bus bearing **Registration Number: WB73E 0179** had collided with **WBSEDCL's Electricity Distribution Network situated beside Amtala Main Road, Bowbazar, North Shantinagar (Landmark: Shil Bari More)** & damaged a considerable portion of it causing huge financial loss to WBSEDCL as well as inconvenience to the people of the surrounding area due to disruption in supply of Electricity which ultimately resulted to the 'No Power' condition. *As reported, the incident took place on 01.02.2024 at around 08:00 am in the morning.* The LT Mobile Van of Subhaspally CCC, immediately after receiving the information, rushed to the spot & isolated the faulty part to avoid any undesirable incident & restored power up to the extent possible; however, around 50 number service connections are still in 'No Power condition' arising out of the aforementioned incident. The alleged bus driver fled from the spot, as gathered.

One LT Pole PCC 8Mtr. long, Porcelain LT Shackle Insulators, associated Iron fittings like- LT Iron Bracket & D-Iron clamps, Earthing installation, approx. 0.200km of ACSR 30sqmm conductors & other associated fittings/accessories & few LT service cables have primarily been assessed to be damaged as a result of the collision; cost of which is provisionally/preliminarily assessed to the tune of **Rs. 22, 000.00** approx. However, WBSEDCL has already started the restoration work at the location which is expected to be completed by the afternoon on 01.02.2024. A formal quotation containing final assessment of demurrage cost will be issued to the bus-owner soon after assessing the actual extent of damage viz. when the restoration work will be completed & the same will be submitted to your good office too.

Hence, your good office is requested to take cognizance of the matter & consider this complain as FIR to take necessary action u/s 139 of the Electricity Act, 2003 (read with amendments) & other relevant laws of the land.

Thanking you,

Encl.: Images of Accident Spot

Received on 01/02/24 at 15:20 hrs vide GSG, P.
EIDEN- 20 dt: 01/02/24 to forward to
E/C GEN RS. for start a case under
proper sec of Law.

Received on 01/02/24 at 20:15 hrs vide GDE NO - 33 and started
Blm PS Case NO - 80/24 Dtd -
01/02/24 u/s 139 of the Indian
Electricity Act 2003 and ordered to
181 Sd/- Sd/- for its investigation.

01/02/24
**OFFICER IN CHARGE
ASHIGHAR OUT POST
Under Bhaktinagar PS
Siliguri Police Commissionerate**

WBSEDCL

Sourav Paul

01/02/2024

Sourav Paul

S/O- Subrata Paul

DE (E) & SM, Subhaspally CCC

Mobile No.: 8900795069

DE (E) & Station Manager

Subhaspally Customer Care Centre

W.B.S.E.D.C.L.

Inspector in-charge
Bhaktinagar Police
Siliguri Police Commissionerate